

# CONTENTS

## OPERATING MANUAL

1. Introduction	1
2. Construction of the Equipment	1
3. Operating Elements	9
4. Functional Description	19
5. Pre-operational Set-up	25
6. Operation	47
7. Working with the Mask Electronics	55
8. Summary of Operation	85
9. Technical Data, Accessories and Documentation	86
10. Measuring Sheets M 1 to M 6	89
11. Curves K 1 to K 6	97
12. Operator Maintenance	105

## APPENDIX A OPERATING MANUAL

1. Oscilloscope	1
2. Densitometer	7
3. Continuous-Tone and Lith Films	8

## APPENDIX B DIAGRAMS

1. Color Computer and Control Section
2. Scanning Unit and Electronics Cabinet
3. Examples for Producing Control Masks

# CONTENTS

<b>1. Introduction</b>	1
<b>2. Construction of the Equipment</b>	1
2. 1. Base Frame	1
2. 2. Power Supply	6
2. 3. Color Computer	7
2. 4. Control Section	7
2. 5. Electronics Cabinet	7
<b>3. Operating Elements</b>	9
3. 1. Color Computer	9
3. 2. Control Section	12
3. 3. White Alignment for Scanning Signal	14
3. 4. Scanning Unit	14
3. 5. Electronics Cabinet	17
<b>4. Functional Description</b>	19
4. 1. Signal Path from Scanning to Exposure	19
4. 2. Signal Path in Mask Scanning Head	22
4. 3. Principle of Electronic Scale Change	24
4. 4. Calculating a Pure, Electronic Scale from the Table Value	24
4. 5. The Electronic Gray Scale	24
<b>5. Pre-operational Set-up</b>	25
5. 1. Changing the Medium and Large Scanning Drums	25
5. 2. Mounting the Scanning Head with the Small Scanning Drum	26
5. 3. Changing the Exposing Heads	26
5. 4. Film-mounting Device	26
5. 5. Film Linearization	28
5. 6. Setting the Film Density	36
5. 7. Selecting and Aligning the Unsharp-masking Filters	36
5. 8. Judging and Classifying Originals	37
5. 9. Mounting the Originals	37
5.10. Selection of the Scanning Apertures	43
5.11. Basic Setting of White Levels for Scanning Head	43
5.12. Basic Setting of Detail Contrast	44
5.13. Basic Setting of Color Correction Values	44
5.14. Positioning the Color Separation on the Film	44
5.15. Setting the Threshold Values for the Mask Scanning Head	46
5.16. Basic Setting of White Levels for Mask Scanning Head	46
<b>6. Operation</b>	47
6. 1. Producing a Set of Four Screened Color Separations	47
6. 2. Producing a Set of Four Continuous-tone Color Separations	51
<b>7. Working with the Mask Electronics</b>	55
7. 1. Possible Applications	55
7. 2. Component Parts of the Mask Electronics and their Method of Operation	55
7. 3. Functions of the Control Mask and the Patch Panel	55
7. 4. Producing a Control Mask	57
7. 5. Positioning the Color Separation relative to the Film	60
7. 6. Adapting the Mask Drum Circumference to the Exposing Drum	61
7. 7. Positioning when Working with the Mask Electronics	61
7. 8. Producing a Color Separation with Electronic Silhouetting	63
7. 9. Silhouetting with a Geometrical Control Mask and Insertion of Lettering	64
7.10. Silhouetting according to Picture Contours	65
7.11. Merging Several Subjects on a Background of Constant Density	67
7.12. Merging of Several Subjects with Different Scales and Insertion of Lettering	69
7.13. Producing a Film by Multiple Exposure	74
7.14. Local Tone and Color Correction	80

<b>8. Summary of Operation</b>	85
8. 1. Summary of Operation for Producing Screened Color Separations	85
8. 2. Summary of Operation for Producing Continuous-tone Color Separations	85
<b>9. Technical Data, Accessories and Documentation</b>	86
9. 1. Technical Data	86
9. 2. Accessories	87
9. 3. Documentation	87
<b>10. Measuring Sheets M 1 to M 6</b>	89
<b>11. Curves K 1 to K 6</b>	97
<b>12. Operator Maintenance</b>	105
12. 1. Localizing Troubles	105
12. 2. Changing the Picture Lamp for Transparency Scanning	105
12. 3. Changing the Picture Lamp for Reflection-copy Scanning	106
12. 4. Changing the Picture Lamp in the Mask Scanning Head	107
12. 5. Changing the Transparency Illumination Lamp and the Starter in the Power Supply	107
12. 6. Changing the Exposing Lamp	107
12. 7. Focusing the Exposing Optics	108
12. 8. Adjusting the Line Thickness (Line Structure)	109
12. 9. Setting the Density Values for Test Exposure	110
12.10. Changing the Test-exposure Lamp in the Exposing Head	110
12.11. Changing the Multipliers	110
12.12. Changing a Pushbutton Lamp	111
12.13. Changing the Pre-exposure Lamp of the Exposing Head for Screened Color Separations	111
12.14. Cleaning and Lubrication	112
12.15. List of Fuses	113